## Work Order ID 57023 Page 1 Wednesday, March 17, 2010 8:17:04 AM Item ID: D3916-5 Accept Setup Start Revision ID: 10.0323 Stop Item Name: Light Rib Start Qty: 18.00 12 Start Date: 3/17/2010 Cust Item ID: Required Date: 3/24/2010 Req'd Qty: 18.00 Customer: Reference: Run Start Date: 10-3-17 Tooling: Process Plan: MF Approvals: Date: Stop QC: Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Draw Draw Plan Reject Accept Reject Insp. Work Center ID Description Run Hours Number Rev. Code Qty Qty Number Stamp Draw Nbr Revision Nbr D3916 A 0.00 Large Fab 0.00 Memo Large Fab 1- Cut tube 54" --10.03.23 2- Bend tube with manuel pipe bender as per dwg d3916 -3- Trim access tube material to finish size as per dwg D3916 -110 QC5- Inspect part completeness to step on W/O Sioles/23 Memo Quality Control

0.00

10.03.23

Identify as per dwg & Stock Location: 505kg

Memo

120

Packaging

Packaging

Dart Aerospace Ltd	Dart	Aeros	pace	Ltd
--------------------	------	-------	------	-----

W/O:			V	VORK ORDER CHANGE	S				
DATE	STEP	PRO	CEDURE CH	HANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									19
Part No		PAR #:							
	R	esolution:	_ Disposit	tion:	QA: N/C C	losed:		_ Date: _	
NCR:		W	ORK OR	DER NON-CONFORMA	NCE (NCI	₹)			
DATE STEP		Description of NC	Corrective Action Section B			Verific	ation	Approval	Approval
	SILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign . Date	Section	Section C	Chief Eng	QC Inspector
		10		in the second se					
									N.

## Work Order ID 57023

Wednesday, March 17, 2010 8:17:04 AM



Page 2

Item ID:

D3916-5

Accept

Setup Start

Stop



Revision ID:

Start Date:

Item Name: Light Rib

3/17/2010

Start Qty: 18.00

Req'd Qty: 18.00



Cust Item ID: Customer:

Draw

Number

Reference:

Approvals:

Required Date: 3/24/2010

Process Plan:

Date:

Tooling:

Date:

Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID

130

Quality Control

Operation Description

QC21- Final Inspection - Work Order Release

Memo

Set Up/ Run Hours

0.00

0.00

Draw Plan Accept Rev. Code Qty

Reject Qty

Run

Reject Number

Insp. Stamp

## **Dart Aerospace Ltd**

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									1.3
								¥	
Part No	:	PAR #:	Fault Cat	tegory:	NCR: Yes	No DQ	A:	_ Date: _	
		esolution:							
NCR:		V	VORK ORI	DER NON-CONFORMA	NCE (NC	3)			
DATE	STEP	Description of NC	Corrective Action Section B			Verific	cation	Approval Chief Eng	Approval
DAIL	SILI	Section A	on A Initial Action Des Chief Eng Chief E		Sign and Date	Section C			QC Inspector
									-
							_		
									. 2

Work Order ID: 57023

Parent Item: D3916-5

Parent Item Name: Light Rib

Comments:

IPP RevA: new issue DD 09.11.23 verified by:EC

as per dwg revA 10.03.15 verified by:EC

IPP Rev:B

Start Date: 3/17/2010

Start Qty: 18.00

Required Date: 3/24/2010

Required Qty: 18.00

Component Item ID/ Item Name M304TS0.500W.049

Replacement Mfg/ Item ID

Purch Purchased

Primary Item Location No

Last Location

114004

114161

Route Seq ID 100

Unit of Measure

Qty on Hand 253,8035 85,2632

Remaining Qty Qty To Pick Issued

Date Issued

Status

Square Tubing

Warehouse Loc Qty Loc Code Location Main Warehouse MAT 253.8034753 113303 10.71832


135.835155

107.25

PD 10.03.23 56.842132


Dart Aerosp	pace	Ltd
-------------	------	-----

W/O:			V	ORK ORDER CHANG	ES				-	
DATE	STEP	PROC	PROCEDURE CHANGE B			By Date		Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
			4							
										11 241
Part No	:	PAR #:	_ Fault Ca	tegory:	_ NCR:	Yes N	lo DQA	:	_ Date: _	
	R	esolution:	_ Disposit	ion:	_ QA: N	/C Clo	sed:		_ Date: _	
NCR:		W	ORK OR	DER NON-CONFORMA	ANCE (	NCR)				
DATE	STEP	Description of NC	Corrective Action Section B					ation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	n C	Chief Eng	QC Inspector
										-
										Te In
						5				
						-				
									e	



Dart Aerosp	ace	Ltd
-------------	-----	-----

		W	ORK ORDER	CHANGES					
STEP	PRO	CEDURE CH	ANGE		Ву	Date (		Approval Chief Eng /	Approval QC Inspector
								X D3916-041 1 D-316-1 7 D3759-1	1 2
	PAR #:	Fault Cat	tegory:	NC	R: Yes N	lo DQ	A:	_ Date: _	
R	esolution:	Dispositi	on:	QA	: N/C Clo	sed:		_ Date: _	
	V	WORK ORI	DER NON-CON	FORMANC	E (NCR)				
CTED	Description of NC Corrective Action Se				Verification			Approval	Approval
SIEP	Section A	Initial Chief Eng			Sign & Date			Chief Eng	QC Inspector
				y					
			3-2-2						
	STEP	PAR #: Resolution:	STEP PAR #: Fault Car  Resolution: Dispositi  WORK ORI  STEP Description of NC Section A Initial Chief Eng	STEP PAR #: Fault Category: Resolution: Disposition:  WORK ORDER NON-CON  STEP Description of NC Section A Chief Eng Chief En	PAR #: Fault Category: NC  Resolution: Disposition: QA  WORK ORDER NON-CONFORMANCI  STEP Description of NC	STEP PAR #: Fault Category: NCR: Yes N Resolution: Disposition: QA: N/C Clo  WORK ORDER NON-CONFORMANCE (NCR)  STEP Description of NC Section A	STEP PAR #: Fault Category: NCR: Yes No DQ/ Resolution: Disposition: QA: N/C Closed:  WORK ORDER NON-CONFORMANCE (NCR)  STEP Description of NC	STEP PAR #: Fault Category: NCR: Yes No DQA: Resolution: Disposition: QA: N/C Closed:  WORK ORDER NON-CONFORMANCE (NCR)  STEP Description of NC Section A Corrective Action Description Chief Eng Chief Eng Section C	STEP PROCEDURE CHANGE By Date Qty Approval Chief Eng Cheff Chief Eng Cheff Chief Chi



Dart Aerospa	ace Lte	d
--------------	---------	---

W/O:			WC	ORK ORDER CHA	ANGES					
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									7	
			и							
Part No	:	PAR #:	Fault Cate	gory:	NC	R: Yes	No DQ	A:	_ Date: _	
	R	esolution:	Dispositio	n:	QA	N/C CI	osed:		Date:	. 9 y
NCR:		,	WORK ORD	ER NON-CONFO	RMANCE	(NCR	)	15-1		W 1
	CTED	Description of NC		Corrective Action	Section B		Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng			Sign & Date		on C	Chief Eng	QC Inspector
NOTE: D	mtn 0 :- 141	at all autologic				1				